

Part-I

Performa For The Safety Of School Building
(To be filled by the Head of School / Institute)

1. Name of the School Sat Paul Mittal School
2. Location URBAN ESTATE, PHASE II DUGRI
3. Plot Area 3106 ACRC
4. Plinth Area 32985 sqh
5. Number of Storey G+G
6. Year of Construction of building 2003-2004
7. Supervision of the qualified Engineer,
the following details may be given:
 - a) Name of the Engineer MANINDER SINGH
 - b) Address OPP. G.N.E COLLEGE, GILL ROAD Ludhiana
 - c) Set of Structure Drawing used in the construction if available
 - d) Name of the Architect M/s Ravinder Khasb + Associate
8. Whether the building has been constructed for the purpose of:
 - a) School (Yes/No) _____
 - b) Residential purpose and converted for use as a school (Yes/No) _____
9. Materials used for Roof:
 - a) R.C.C. slabs (Yes/No) _____
 - b) R.S. Joists and Battens (Yes/No) _____
 - c) Wooden Joists and Battens (Yes/No) _____
10. Materials used for Walls:
 - a) Mud Mortar (Yes/No) _____
 - b) Cement Mortar (Yes/No) _____
 - c) Plaster (i) Lime Mortar (Yes/No) _____
(ii) Cement Mortar (Yes/No) _____
11. Flooring:
 - a) Conglomerate (Yes/No) _____
 - b) Terrace (Yes/No) _____
 - c) Brick Paving (Yes/No) Kota Stone
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows.

Ravinder Khasb

Signature with stamp of
The Head of the School / Institute.



Part-II


(To be filled by S.D.E. of P.W.D. B&R Department)


I have visited the above mentioned school on 5-5-23 and have visually inspected it from all angles of safety and I found it fit for normal use as School building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or eaves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31-3-24
(indicate year upto which it can be used).


Sub Divisional Engineer
Constn. Sub Division No.1,
Sub Div. of P.W.D. B & R Ludhiana




ਪਿਠ ਅੰਕਣ ਨੰ. 47-48

ਮਿਤੀ: 08/05/23

1. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ Sat Paul Mittal School Urban Estate, Phase II Dugri Ludhiana ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅੰਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ ਨਿ. ਵਿ. ਭ ਤੇ ਮ ਸਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।


Sub Divisional Engineer
Constn. Sub Division No.1,
P.W.D. B & R Ludhiana